

09/15/14

RETRIEVER PAYMENT SYSTEMS

" DON'T BE SOLD / USED/ OBSOLETE EQUIPMENT "

Sales Reps. who are proposing to Sell the Terminals shown below to a Business Owner are Usually Selling them **"USED EQUIPMENT", Usually at NEW EQUIPMENT PRICES.** Many Sales Reps don't CARE about your business, just Their Commission. A Professional Sales Rep. Would Supply you a NEW High Tech Terminal. The only reason for a Sales Rep. to Supply you one of the Terminals shown below is because their available to the Rep. At a Lower Cost because their Used. Would you pay the same for a 1986 Car as you would for a 2015 Car ? All the Terminals shown below have been Upgraded by the Manufacturer with much Faster, Larger Memory Terminals that can do many more types of features for your business, that are **"Payment Card Industry (PCI) COMPLIANT & CERTIFIED, & EMV SMART CARD COMPLIANT."**

" OBSOLETE - NON PCI - EMV COMPLIANT TERMINALS "

1. THALES: Talento 2U,2UD,4UD, Talento Pin Pad, OBSOLETE as of 11/01/07.
2. NURIT: 2050,2060,2080,2085,2090,3000,3010,3020,8000,8010,8020,8320,8400
3. VERIFONE: ZONJR, TR330, TR380, TR420, TR460, OMNI396, OMNI470, OMNI3010, OMNI3200, VERIFONE: OMNI3730, 3740, 3750, OMNI3200SE, OMNI3210, OMNI3300, ZON JRXL, 300XL, VERIFONE: VX510, VX510DC, VX510LE, VX570, VX570DC, VX610.
4. HYPERCOM: T7P, T7E, T77, T7PLUS, T4100, ICE5000, ICE5500, ICE6000.
5. EQUINOX: T4205, T4210, T4220, M4230.

" OBSOLETE: = ILLEGAL FOR BANKS TO RE-PROGRAM EQUIPMENT."

"OBSOLETE - NON PCI/ EMV COMPLIANT INTERNAL PIN PADS "

1. VERIFONE OMNI 3730, 3740, 3750,
2. VERIFONE VX510, VX510DC, VX510LE, VX570, VX570DC, VX610.
3. NURIT 2085, 2090, 3000, 3010, 3020, 8000, 8010, 8020, 8320, 8400
4. EQUINOX T4100, T4205, T4210, T4220, M4230.

The Above Listed Terminals with Internal Pin Pads **" CAN NOT "** be Re-Encrypted for Debit. They No Longer Meet Debit Network Security Requirements. An External Pin Pad must Be Used to Process Debit Pin Based Transactions for all New Merchant Accounts on the Above listed Terminals, as **"These Internal Pin Pads are Not PCI Compliant Pin Pads."**

" OBSOLETE - USED -- ILLEGAL PIN PADS "

Talento Pin Pad, VERIFONE 101*,201*,1000*,1000SE*, HYPERCOM S7,S8,S9, P1300, P1310, NURIT 202, 222, 252, 292 Pin Pads Are All Obsolete & Illegal.

*(The VERIFONE 1000SE/180 is PCI COMPLIANT, & REPLACES THIS PIN PAD.)

+All PIN PADS with DUKPT Encryption Stickers on bottom of Pin Pad.

The Pin Pads shown above **"CAN NOT"** be **"RE-ENCRYPTED"** & Re-used for Debit Card Sales. The Pin Pads shown above will become Obsolete as of JULY 1, 2010, for any Merchant currently processing and using one of these Pin Pads. New Pin Pads Will be Required by the Debit Networks for Increased Encryption Security. Do NOT Allow a Sales Rep. to Sell you one of the Pin Pads listed above, as they are NOT PCI Debit Certified by the Debit Networks and will become Obsolete at the End of 2009. If the Pin Pad No Longer Works, It must be Replaced with a New PCI Compliant Pin Pad.

+ALL PIN PADS WITH DUKPT ENCRYPTION STICKERS ON THE BOTTOM OF THE PAD.

States can Impose large Fines for merchants using terminals that do Not Print the Last 4 Card Numbers Only on Customers & Merchants Receipt.

ALL MERCHANTS MUST BE PCI & EMV CARD COMPLIANT & CERTIFIED WITH VISA/MASTERCARD EACH YEAR or be FINED MONTHLY. THIS IS NOT AN OPTION!

Call TOM MAY @ (888) 325-7677